October report

\bigcirc	Yard waste pickup
\bigcirc	McGills sewer cleaning service in to do annual sewer cleaning
\bigcirc	Started boiler at HGCC
\bigcirc	Removed water meter at tufts bay campground and rodeo grounds. Blew out lines.
\bigcirc	Removed light pole on cliff edge at tufts bay campground
\bigcirc	Installed snow fence
\bigcirc	Placed parking stops at HGCC
\bigcirc	Started boiler at HGCC
\bigcirc	Removed water meter at tufts bay campground and rodeo grounds. Blew out lines.
\bigcirc	Removed light pole on cliff edge at tufts bay campground
\bigcirc	Installed snow fence
\bigcirc	Placed parking stops at HGCC
\bigcirc	Removed speed bumps and signs
\bigcirc	Replaced flags at the entrance to the village
\bigcirc	Added reflective strips to the village office stairs
\bigcirc	Started boiler at office
\bigcirc	Started furnace at the rink
\bigcirc	Fall tree trimming and removal

\bigcirc	Replaced flags at the entrance to the village
\bigcirc	Added reflective strips to the village office stairs
\bigcirc	Started boiler at office
\bigcirc	Started furnace at the rink
\bigcirc	Fall tree trimming and removal
\bigcirc	Fixed shower that wasn't draining at HGCC
\bigcirc	HGCC sprinkler lines blown out
0	Lights at orchard went out due to underground wiring issues. Need to look into replacement lights.
\bigcirc	Getting more comfortable in the grader before the snow comes